

---

**From:** Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFF136]  
**Sent:** 6/22/2015 11:49:50 AM  
**To:** Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]  
**CC:** John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=John171]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]  
**Subject:** RE: Ash Pond ABC inspection 06/22/15  
**Attachments:** 20150622112148688.pdf

Attached.

**No Discharge** at C Pond. Some standing water around weir of Pond C. Water level inside bottom of weir is below pipe.

There is seeping and dripping inside C Pond discharge weir, above the "board", and only in one corner.

No standing water behind sand-bags at 'A', the standing water has receded along with the southern edge of the 'A' pond interior. The NE end of A Pond is holding water in pathway created from matting/equipment activity, noticeable depression in this section from activity related to drilling.

No standing water behind sand-bags at 'B' pond.

Standing water is still present at the toe of the slope between 'A' and 'B' pond sections.

Precipitation was 1.53" from a storm events 6/19 – 6/21.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)